

Checklist for ILEC Instrument Shipping

Please pack your instrument as follows:

- Remove and keep all mounting hardware and cables (do not send !)
- Tape your return address to the instrument case
- Enclose a brief explanation of what's wrong
- Place in a plastic bag, not air-tight, do not plug pneumatic ports
- make sure its well padded (blister pack or peanuts)

Please send your SN10 to:

ILEC GmbH - Telephone (0921)13733
Friedrich-Puchta St. 6
D-95444 Bayreuth, Germany

Mark the package exterior:

- Mark the package "Civil Aircraft Instruments for Repair TARIC 8803 90 91" on the customs slip, with value Euro 200.
- Make sure ILEC's telephone number is marked on the package, in the address, as above

Please ship by **US Airmail service**. Please **** DO NOT **** use UPS, Fedex, or US Express mail, as this is actually slower; if you use an express service your instrument will sit in Frankfurt customs for some time...